

Examples of our work carried out in 2009 – 2016

Motoryacht, 27 m, painting topsides in AlexSeal. Owner's Surveyor. (#401131)

Sailing Yacht of high pedigree, 25 m, painting topsides in AlexSeal. Owner's Surveyor. (#206221)

Motoryacht of high pedigree, 26 m, major refit work. Inspection of refit and reporting findings to owners. (#207091)

Motoryacht, 30 m, major damages following flooding and salvage. Assessing damages, finding agreement with salvors, arranging vessel to transfer to next safe port, arranging for repair quotations, reporting to insurers. (#020931)

Motorsailer, 40 m, major damages following sinking. Arranging salvage and initial actions to prevent growth of damages, assessing damages, devising repair methodology, reporting to insurers. (#209111)

Motoryacht, 37 m, major refit. Assessing refit work, negotiating with repairers, coming to revised agreements, overseeing completion of refit work, reporting to owners. (#029855)

Motoryacht, 30 m, preparing vessel for obtaining class and commercial status, carrying through class approval procedure, reporting to owners. (#204132)

Motoryacht of high pedigree, 46 m, Evaluating some yard work carried out during refit, based on reports. Assessing responsibility level of sides involved. Reporting to owners. (#206012)

Motorsailer, 43 m, major damage following yard accident, overseeing repairs and acceptance of repairs by owners. Reporting to insurers. (#033679)

Semi Custom Superyacht, 46m, Evaluating yard works during construction and financial tracking. Reporting to financing company. (#206222)

Motoryacht, 37 m, Assessing constructional issues, which led to repetitive fire on board. Advise about improvements. Reporting to insurers. (#307031)

Motoryacht, 38 m, Assessing Vessel's condition and refit work. Reporting to insurers. (#402071)

Motoryacht, 32 m, Assessing damages inflicted during a rough transfer. Reporting to insurers. (#212211)

Motoryacht, 38 m, Assessing damages to Vessel due to a collision. Reporting to insurers. (#309051)

Motoryacht, 27 m, Pre Purchase Condition Survey. Reporting to buyer. (#401131)

Motoryacht, 40 m, Arrange search for Vessel, believed to have been embezzled. Reporting to insurers. (#031574)

Sailing Yacht, 38 m, Survey damage to mast, develop repair methodology, carry out stability checks of Vessel, oversee drawing of mast. Reporting to insurers. (#027380)

Motoryacht, 33 m, Survey damages due to ground contact with corals, develop repair methodology. Reporting to insurers. (#029896)

Sailing Yacht, replica of high pedigree, 36 m, Oversee launching procedures, survey some critical issues on board, carry out valuation survey. Reporting to owners. (#307271)

Sailing Yacht, 28 m, Survey repairs, recommend repair procedures, contribute to agreement between Owner and Repairers. Reporting to owners. (#027713)

Sailing Yacht, 29 m, Recover embezzled vessel. Reporting to owners. (#033422)

Motoryacht, 27 m, Pre Purchase Condition Survey. Reporting to buyer. (#031481)

Motoryacht, 26 m, Pre Purchase Condition Survey. Reporting to buyer. (#030016)

Motoryacht of high pedigree, 27 m, damages to hull and third party due to collapsing hangar. Evaluate reason and costs on behalf of insurers. (#020833)

Sailing Yacht of high pedigree, 46 m, damages to hull at drydocking. Evaluate responsibilities and costs on behalf of insurers. (#503131)

Motoryacht, 63 m, Evaluate and report single transfer risks and recommendations on behalf of insurers. (#507061)

Motoryacht, 38 m, Oversee and organize sunken vessel recovery on behalf of insurers. (#508211)

Motoryacht, 27 m, Pre Purchase Condition Survey. Reporting to buyer. (#603102)

Motoryacht, 40 m, Evaluation of the recommended list of major repair works to be carried out. (#603222)
06032202

Motoryacht, 40 m, Pre Purchase Condition Survey. Reporting to buyer. (#601201)

Motoryacht, 29 m, Pre Purchase Condition Survey. Reporting to buyer. (#604291)

Motoryacht, 23 m, Pre Purchase Condition Survey. Reporting to buyer. (#605131)

Motoryacht, 25 m, Valuation Survey. Reporting to owner. (#605231)

Motoryacht, 22 m, Evaluation of repairs. Reporting to manufacturer. (#605271)

Sailing Yacht, 29 m, Analysing damages of 39 m carbon mast and Reporting to Insurers. (#607131)

Motoryacht, 22 m, Inspection of irregularities on aluminium hull plates. Reporting to Insurers. (#608081)

Sailing Yacht, 28 m, Assess cause of water ingress and extent of damages. Report to insurers. (#608092)

Sailing Yacht, 29 m, Assess damages to Vessel due to a TP collision and reasonable repair costs. Reporting to Insurers. (#608221)

Sailing Yacht, 31 m, Analysing damages of 40 m carbon mast and Reporting to Insurers. (610251)

Motor Yacht, 26 m, Surveying and consulting teak deck renewing process and Reporting to owner. (611111).

Motoryacht, 49 m, Transfer management. (#612151)

Motoryacht, 26 m, Pre Purchase Condition Survey. Reporting to buyer. (#702081)

Motoryacht, 33 m, Submerged Hull and Internal Grid System Condition Survey. Reporting to owner. (#703271)

Dr. Yusuf Civelekoğlu, CMI